



Анализатор серы COSA SF6 Purity Pro

Технические характеристики

Архангельск (8182)63-90-72
Астана +7(7172)727-132
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06
Ижевск (3412)26-03-58
Казань (843)206-01-48

Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81
Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41

Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16
Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78

Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

SF6 Purity Pro™

Light Speed Measurement



Description:

The COSA SF6 Purity Pro is the fastest and most accurate instrument for measuring SF6 gas purity in different SF6 gas applications.



Utilizing the SF6 Purity Pro's small size and light weight it is very easy to carry and transport. The SF6 Purity Pro also requires zero warm-up time increasing your efficiency and costs in the field. Truly a great asset for making your measurements when time and accuracy are of great importance.

The COSA SF6 Purity Pro also works well with a Portable Dew Point Meter (XPDM) when a dew point measurement is also required.

SF6 Purity Pro™
Light Speed Measurement

SF6 Purity Pro™

Applications:

- Electrical Substations
- Circuit Breakers
- Transformers
- Switchgear
- SF6 Gas Recycling Units
- Electron Microscopes
- Particle Accelerators
- Magnesium Production and Casting



Benefits:

- Small Size
- Light Weight
- No Warm Up Time
- Quick Response
- Easy Operation
- 20 Hours of Battery Life
- Stores 100 Readings
- High Pressure Sampling
- Full Range 0-100%



SF6 Purity Pro™

Specifications:

Measuring Gas	SF6 (Sulphur Hexafluoride)
Measuring Range:	0-100 vol. %
Resolution:	0.1%
Indication Accuracy: +/- vol. %	+/- 1 vol. %
Detection:	Interferometer
Sampling Method:	Internal Pump
Sampling Pressure:	1.5 to 7.0 bar inlet pressure
Flow Rate:	>0.4 l/min
Alarm Indication:	Buzzer, LCD-Notification
Alarm Types:	System Error, Low Battery, Sensor Connection, Calibration Error
Response Time:	Approx. 30 seconds
Dimensions & Weight:	345 x 245 x 185 mm - Approximately 12 lbs (5.5kg)

SF6 Purity Pro™
Light Speed Measurement

По вопросам продажи и поддержки обращайтесь:

Архангельск (8182)63-90-72
Астана +7(7172)727-132
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06
Ижевск (3412)26-03-58
Казань (843)206-01-48

Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81
Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41

Нижегород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16
Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78

Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

Единый адрес для всех регионов: cso@nt-rt.ru || www.cosa.nt-rt.ru